



QBE3 - View taken from the approach pathway of the remains of the building. The stone plinth with partial stone chimney is visible. Widespread vegetation has established itself within the confines of the building footprint.



QBE3 - Remnants of the staircase of what would have been considered the front door to the building. Note the excessive building rubble as a result of the demolition and dismantling of the building.



QBE3 – The remaining walls of outbuildings walls are damaged, with exposed brickwork and vegetation growing in the walls.



QBE3 – There are no doors, windows, roofs or fittings left and the remaining walls appear to have started crumbling in places.



QBE3 – The chimney is partially intact and built of bricks with some stone masonry. The bricks have become brittle, while the stonework has remained in a reasonable condition.



QBE3 – Broken clay roof tile that was presumably used as the roof covering of the farmstead prior to demolition.



View of the typical dense vegetation limiting access to the sites. Access is gained mainly via foot paths.



The site is littered with building rubble where buildings have been demolished and stripped bare.



QBE3 – The existing building service infrastructure is in poor condition.



QBE4 - Transmission tower positioned at point QBE4. The facility is accessed via a narrow bush track and is fenced off with razor wire for security purposes.