


Photographs of Erosion along the Skoenmakers River

Report Number 472748





 **srk** consulting

Skoenmakers River Rehabilitation
Evidence of erosion along the Skoenmakers river

Project No.
472748

Figure 1: Evidence of erosion along the Skoenmakers River



 **srk** consulting

Skoenmakers River Rehabilitation
Erosion on the bank of the Skoenmakers River

Project
No.
472748

Figure 2: Erosion on the bank of the Skoenmakers River.



	Skoenmakers River Rehabilitation Bank Erosion	Project No. 472748
---	---	--------------------------

Figure 3: Bank Erosion



	Skoenmakers River Rehabilitation Erosion along an embankment	Project No. 472748
---	--	--------------------------

Figure 4: Erosion along an embankment.



 **srk** consulting

Skoenmakers River Rehabilitation
Skoenmakers river bank erosion.

Project
No.
472748

Figure 5: Skoenmakers river bank erosion.